## **Two-Week Look-Ahead Schedule**

**Contractor: BLD Services LLC** 

Project Name and Number: #30229, Carrollton Basin No. 1

**Submitted By: Nicholas Dupaquier** 

Submission Date: 10/10/25

Time Period Covered: 10/10/25-10/24/25

--

## **Planned Work Activities**

Date	Block Number and Street Name	Work to be Performed	Notes
10/10/25-	2500 S Carrollton	LAT CIPP	TBD – <b>BLD</b>
10/24/25			
10/10/25-	9400 Oleander St	CIPP	Scheduled for 10/14/25 – <b>BLD</b>
10/24/25			
10/10/25-	8300 S Claiborne	Restoration	Site Cleanup – <b>C&amp;M</b>
10/24/25			
10/10/25-	8500 S Claiborne	Restoration	Site Cleanup – <b>C&amp;M</b>
10/24/25			
10/10/25-	3800 Cambronne	Restoration	Forming/ pouring sidewalk– <b>C&amp;M</b>
10/24/25			
10/10/25-	8900 S Claiborne	CCTV	TBD - <b>BLD</b>
10/24/25			
10/10/25-	2700 Cherry	Restoration	Removal/ grade/ pour – <b>C&amp;M</b>
10/24/25			
10/10/25-	9000 Nelson	Restoration	Removal/ grade/ pour – <b>C&amp;M</b>
10/24/25			
10/10/25-	8600 Oleander	Restoration	Removal/ grade/ pour – <b>C&amp;M</b>
10/24/25			

No tree impacts anticipated in the next 2 weeks

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each workday; repairs are scheduled to take ~1day each.

Restoration Work on-going across the basin.

**BLD TRACKING: 96% COMPLETE**